	N DR		PCN Notification Document #FM5208-FM5200B series PCN Issue Date: 2023/11/24 PCN#: 20231124002		
Title of Change:		FM520B-FM5200B series PCN			
Proposed first ship date		2023/11/24			
Contact information:		Please contact Rectron Sales Office or visit www.rectron.com for nearest contact information.			
Samples:		Please contact Rectron Sales Office or visit www.rectron.com for nearest contact information. Samples delivery timing will be subject to request date, sample quantity and special customer packing/label requirements.			
Additional Reliability Data:		Please contact Rectron Sales Office or visit www.rectron.com for nearest contact information.			
Type of notification:		This is a Final Product/Process Change Notification (FPCN) sent to customers. FPCNs are issued 90 days prior to implementation of the change. Rectron will consider this change accepted, unless an inquiry is made in writing within 30 days of delivery of this notice. To do so, please visit www.rectron.com for nearest contact information			
Change Part Identification:		Datasheet revision change per below			
Change Category:		□ Material □Machine/Tooling ☑Method □Manufacture site □Man			
Change Sub-Category(s):		Imanufacturing Site Transfer     Imaterial Change     Imanufacturing Process Change     Imanufacturing Process Change     Imanufacturing Process Change     Shipping/Packaging/Marking     Imanufacturing Site Additi     Imanufacturing Site Additi			
Last order date for previous version		/			
Description and Purpose:		The IFSM and VF limits set in the original datasheet were published in error. The incorrect limits will be adjusted according to the actual electrical performance, so that the datasheet will match the actual process. No fit, form or function changes have been made to the actual products.			
Point:	Change		Before		After
Specification specification standard	IFSM	superingood of rated ead (JEDEC marries)	la <sub>BM</sub> 200 Arps	superimposed on rated load (JEUEC metho	
Electrical Characteristic Summary:	VF	Constructions Constru			
List of Affected Parts:		FM520B-FM5200B series			
Part Number	Suggest New Part Number	Addition		Mark	
FM520B	FM520B				
FM530B	FM530B				
FM540B	FM540B				
FM550B	FM550B				
FM560B	FM560B				
FM580B	FM580B				
FM5100B	FM5100B				
FM5150B	FM5150B				
FM5200B	FM5200B				
V-AE19A1	i.				